

Hayabusa Regulator/Rectifier to Generator wiring

On some occasions standard crank sensor connectors have been damaged. This information has been produced so you can check continuity between the ECU and engine on the Hayabusa. They must be wired the correct way round, or the engine will not run.

These instructions should be sufficient to produce a wiring loom to integrate the changing circuit into most aftermarket systems.

